
## Radielegical Pestings Mean Yeu

Whether you work in a controlled area routinely or once a year, signs, postings, tape boundaries, and labels with magenta or black radiation symbols on a yellow background apply to you.

Areas that are no longer used for radiological work may have historical contamination. If you suspect that historical or other types of unposted contamination



exist, notify your supervisor or area radiological control technician. If you or another worker may have become contaminated, notify your supervisor or RCT immediately.

Posted radiological control requirements must be followed as long as signs are in place.

Never disregard radiological postings because you think they are going to be updated or removed.

Los Alamos National Laboratory Occurrence Investigation Group Mail Stop K999 Attention: Meredith Gerke